

FIELD INSPECTION REPORT

Date of Inspection :	3/12/2020	District:	MADHUBANI
Division :	JHANJAR PUR	Length (km):	4.60 km
Name of the Road:	KAKO TO OJHAUL		
Scheme/Programme:	MAINTENANCE	3054 (MR)	
Package No.:	MR-2/Jhanjar Pur/01/2018	Road Id No.:	31909800828
Status of the Project:	Ongoing/Completed/Under Maintenance (Work in Progress)		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
S.No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	✓ S/U	
b)	Condition of Surfacing	✓ S/U	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	ND	

Overall Rating :

Satisfactory (S)	"S"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

[Signature]
3/12/20
(Signature)

NAME: MD GYASUDDIN

DESIGNATION: (ASSISTANT ENGINEER)