FIELD INSPECTION REPORT

Date of Inspection: 03/12/2020 District: Madhusani Division: Thanshorper Length (km): 4.750 km				
	and the same of th	Khneur path	To Raja Kharwara pa	₽h
	Programme:	MAINTENANCE	10	000
		mihorpur/01/2018	Road Id No.: 3190 98 00	87.2
Status of the Project: Work is a case of:		Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance		
Sli No.		Parameters to be checked		Remarks
	Payement	234,000	78827 W. S	A Section 1
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
I)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainag	ic		
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furnitus	re		41 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No onsoing
4.5	Compliance History			0 0
a)	Status of ATR's & any others			No

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

(Signature)

NAME: Prakash Kant Pankaj DESIGNATION: Assistant Engineer,

Scanned by CamScanner