

FIELD INSPECTION REPORT

Date of Inspection : 02 - 12 - 2020	District: <u>Gaya</u>
Division : <u>Tikari</u>	Length (km): <u>2.900</u>
Name of the Road: <u>Repair of Road from Gaya Khatyanj Road to Bararah</u>	
Scheme/Programme:	MAINTENANCE
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		✓ S/U
b)	Condition of Surfacing		✓ S/U
c)	Riding Quality		✓ S/U
d)	Road Camber		✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		— Yes/No
f)	Contraction Joints provided or not (CC Pavement)		— Yes/No
g)	Compaction of flank/slope & raincuts if any		✓ Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		— S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		— S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m	✓ Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

[Signature]
2.12.20
X-

[Signature]
02-12-2020
A.E.

[Signature]
21/12/20
EE
(Signature)
EE