

FIELD INSPECTION REPORT

Date of Inspection:- 03/12/2020		District:- Sheohar
Division:- RWD, Works Div. Sheohar		Length (km):- 3.75 km
Name of the Road:- Sheohar to Mahuariya		
Scheme/Programme:-		MAINTENANCE MA 3054
Package No.:-		Road Id No.: 31608100815
Status of the Project:		Ongoing/Completed/Under Maintenance ✓
Work is a case of:		New Connectivity/Up gradation/ Maintenance ✓
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutments & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railing/slab/approach for bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sing board/informatory/cautionary Board/ Km & 200m stones/Pavement road marking are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Name:- Ram Binay Singh

03/12/2020
(Signature)

DESIGNATION:- A.E