

3054M/R old Patney.
FIELD INSPECTION REPORT

Date of Inspection : 02.12.2020	District: Siwan
Division : SINAM-2	Length (km): 1.80 KM
Name of the Road: Mairwa Railway Dhalg to Chitrakoot Bank	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S S/U
b)	Condition of Surfacing	U S/U
c)	Riding Quality	S S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	HA Yes/No
f)	Contraction Joints provided or not (CC Pavement)	HA Yes/No
g)	Compaction of flank/slope & raincuts if any	HA Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

NAME:

DESIGNATION:

Signature
26/12/20
Executive Engineer
Rural Work Department
Work Division Siwan-2

Signature
02.12.20
A.E