


FIELD INSPECTION REPORT

Date of Inspection: 02.12.2020		District: Katihar.	
Division : Katihar		Length (KM) :	
Name of Road:	Kursela-Saras, Chandpur to Bhadrayatra Via Dumariya Road		
Scheme/ Programme:	MAINTENANCE		
Package No.	Road ID No. 21105500829		
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/ Up Gradation/ Maintenance		
Sl.No	Parameters to be Checked		Remarks
1	Pavement		
a)	Road Junction Condition		✓ S/U
b)	Condition of Surfacing		✓ S/U
c)	Riding Quality		✓ S/U
d)	Road Camber		✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)		✓ Yes/No
g)	Compaction of flank/slope & raincuts if any		✓ Yes/No
2	Cross Drainage		
a)	Condition of headwalls in Humepipe culverts including its painting		✓ S/SRI/U
b)	Condition of Abutment & Wings walls, Slab in RCC culverts		✓ S/SRI/U
c)	Condition of railings/slabs/approach for Bridges		✓ S/SRI/U
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.		✓ Yes/No
4	Compliance History		
a)	Status of ATR & any others		NO
Overall Grading:		Satisfactory (S)	S
		Satisfactory but requires Improvement(SRI)	
		Unsatisfactory (U)	

Name: PAPPU KUMAR
Designation- J.E/ Samele


 2.12.2020
 (Signature)

R.W.D. Works Div., Katihar