

## FIELD INSPECTION REPORT

Date of Inspection:	02-12-2020	District:	Dankhanga
Division:	Biraul	Length(Km):	3.50
Name of Road:	Kahua To Missi		
Scheme/Programme:	Maintenance		
Package No.	MR- 3054	Road Id No.	
Status of the Project:	Ongoing/Completed/ Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

  

S No.	Parameters to be Checked	Remarks
<b>1</b>	<b>Pavement</b>	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank /slope & raincuts if any	✓ Yes/No
<b>2</b>	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slabs in RCC culverts	S/SRI/U
c)	Condition of railing /slabs/ approach for Bridges	S/SRI/U
<b>3</b>	<b>Road Furniture</b>	
a)	Whethersign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	Yes/No ✓
<b>3</b>	<b>Compliance History</b>	
a)	Status of ATR's & any others	NO ATR
Overall Rating:		
Satisfactory (S)		
Satisfactory but requires Improvement (SRI)		SRI
Unsatisfactory (U)		

Name:

Designation:

*Kamal*  
02/12/2020  
JE

*Di*  
02/12/2020  
AB

(Signature)