

FIELD INSPECTION REPORT

Date of Inspection : 3-12-2020		District: Buxar	
Division : Buxar		Length (km): 2.755 Km	
Name of the Road: Chhatapur to Gogahi maniq road.			
Scheme/Programme: MAINTENANCE		MR 78054 new maintenance policy 2018	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance Completed.	
Work is a case of:		New Connectivity/Up gradation/ Maintenance maintenance.	


Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained 200m	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Mubarek Hussain Ansari

NAME:


 3-12-2020
 (Signature)

R.W.D. works section
Rajpur