## FIELD INSPECTION REPORT

Date of Inspection : O	2 12 2012	District: Sheikhpura	
Division: Sheikhbura		Length (km): 6.800 km	
Name of the Road:		ak To Bhadeli	
Scheme/Programme:			
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

SI. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	∨ S/U	
b)	Condition of Surfacing	√S/U	
c)	Riding Quality	√S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No _	NA -
f)	Contraction Joints provided or not (CC Pavement)	Yes/No -	NA -
g)	Compaction of flank/slope & raincuts if any	VYes/No	Raincuts
2,	Cross Drainage	STATE E	Some places
a)	Condition of head walls in Hume pipe culverts including its painting	THE RESERVE OF THE PARTY OF THE	NA -
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		NA-
c)	Condition of railings/slab/approach for Bridges	S/SRI/U -	NA-
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	200m
1034.00	Compliance History		
a)	Status of ATR's & any others		

Overall Rating

Satisfactory (S)	-	
Satisfactory but requires Improvement (SRI)	SRI	
Unsatisfactory (U)		

(Signature)

NAME: SANGRAM HEMBROM

DESIGNATION: A. E.