FIELD INSPECTION REPORT

- CT	\forall \land \circ \circ \circ \circ \circ	District: madhybani	
Date of Inspection: 0 3- 12 - 2020		Length (km): 4.400 km	
	agar	to NH-105 Selibeli	
A STATE OF THE PERSON NAMED IN COLUMN 2 IN			
Scheme/Programme:	MAINTENANCE	Dead Id No. 7 10005 5 110	
Package No.:	(A)	Road Id No.: 3.19097 E+12	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/	Up gradation/ Maintenance	- A.S 2

Vork is a case of: Ne		New Confectivity/Op graduation	Remarks
SI. No.		Parameters to be checked	Nelliai Ks
1.	Pavement	The state of the s	
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber -		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f)	Contraction Joints provided or not (CC Pavement)		Xes/No
	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drain	iage –	
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furni		r
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4.	Complianc	e History	
a)	Status of A	FR's & any others	

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: CHITRANJAN RAHUL

DESIGNATION: J.E, - Bosopats: