

FIELD INSPECTION REPORT

Date of Inspection : 08.12.2020	District : GAYA
Division : Neemchak Bathani	Length (Km.) : 3.5
Scheme/Programme:	MAINTENANCE Gagg-Nawada Rd to Rasalpur to mashaohakala rd
Package No. : MR-N/2019-20 Neemchak Bathani/02	Road Id No. :
Status of the Project :	Ongoing/Completed/Under Maintenance
Work is a case of :	New Connectivity/Up gradation/Maintenance

Sl. No.	Parameters to be checked	Remarks
---------	--------------------------	---------

1	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No

2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U

3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No

4	Compliance History	
a)	Status of ATR's & any others.	

Overall Rating :	
Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Note : Work has been not started.

Ram Basu mahato
J.E

3.12.2020
J.E