

FIELD INSPECTION REPORT

Date of Inspection :	21/12/2020	District:	Madhepura
Division :	RWD Udakshingari	Length (km):	5.230 K.M
Name of the Road:	Jagdishpur Halt TO Alamnagar Path		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	2100480280815
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U only pcc Pavement	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No O.G	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No O.G	
4.	Compliance History		
a)	Status of ATR's & any others	No	

Overall Rating :

Satisfactory (S)	O.G. (S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

03/12/2020
(Signature)
J-E

NAME:

Ravish. Ranjan

J-E Alamnagar.

(4)

FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020		District: Madhepura	
Division : UdaKishore		Length (km): 5.230	
Name of the Road: Jagdishpur Haat to Alamnagar Path			
Scheme/Programme: MAINTENANCE			
Package No.:		Road Id No.: 2100480080015	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance			
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement	S/U	
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	Yes/No	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any		
2.	Cross Drainage	S/SRI/U	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges		
3.	Road Furniture	Yes/No	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.	Compliance History	No	
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	Work in progress
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


 (Signature)
 E. E.
 R. W. UdaKishore

NAME:

Ravi Ratan Ravi