

(1)

FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020		District: Madhepura	
Division : UdaKishanganj		Length (km): 4.500 Km	
Name of the Road: NH-106 to Sindwani Path			
Scheme/Programme: MAINTENANCE		Road Id No.: 2100480080016	
Package No.:		Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others		

only
sign board
and informa-
tory board
fixed.

Overall Rating :

Satisfactory (S)	} Work not start
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Note: → work not start

(Signature)

E. L. Q. W. B.

UdaKishanganj

NAME:

Ram Ratan Ram

FIELD INSPECTION REPORT

Date of Inspection : 02-12-2020	District: MADHEPUR
Division : UDAKISHUNGANJ	Length (km): 4.500
Name of the Road: NH 106 TO SINDWARI	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.: 2100480080016
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	S/U
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	S/SRI/U
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	Yes/No
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

25/12-2020
(Signature)
NAME- VAISHANKAR PRASAD
J.E.
BLOCK- GWALPURA -