

FIELD INSPECTION REPORT

| | | |
|---|--|---|
| Date of Inspection : 3.12.2020 | | District : GAYA |
| Division : Neemchak Bathani | | Length (Km. : 4.30 km) |
| Scheme/Programme: | | MAINTENANCE - Gohardaha Rd to Nauli |
| Package No. : MR-N / 2019-20 Nimchak Bathani / 03 | | Road Id No. : |
| Status of the Project : . | | Ongoing/Completed/Under Maintenance |
| Work is a case of : | | New Connectivity/Up gradation/Maintenance |
| Sl. No. | Parameters to be checked | Remarks |
| 1 | Pavement | |
| a) | Road Junction condition | S/U |
| b) | Condition of Surfacing | S/U |
| c) | Riding Quality | S/U |
| d) | Road Camber | S/U |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | Yes/No |
| f) | Contraction Joints provided or not (CC Pavement) | Yes/No |
| g) | Compaction of flank/slope & raincuts if any | Yes/No |
| 2 | Cross Drainage | |
| a) | Condition of head walls in Hume pipe culverts including its painting | S/SRI/U |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | S/SRI/U |
| c) | Condition of railings/slab/approach for Bridges | S/SRI/U |
| 3 | Road Furniture | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No |
| 4 | Compliance History | |
| a) | Status of ATR's & any others. | |

Overall Rating :

| | |
|---|--|
| Satisfactory (S) | |
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | |

Note - Work has been not started.

Ram Babu mahto
J.E

Am
3.12.2020
J.E