

FIELD INSPECTION REPORT

Date of Inspection : 03.12.20	District: Gaya
Division : Gaya	Length (km): 4.250 K.M.
Name of the Road: Rajabigha to Tetariya	
Scheme/Programme: MAINTENANCE	New Maintenance Policy 2018
Package No.: MR-N/19-20/Gaya/10	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	ongoing
Work is a case of:	New Connectivity/Up gradation/ Maintenance Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage Not started	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m ✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

V. H. W.
13/12/20
(Signature)