(3)

## FIELD INSPECTION REPORT

Date of I	nspection:	02/12/	District: Patra	
Division: Pota			1 10 2 2 2	
Name of	the Road: Mok	ammadbux	Se miracle of the	D+I
Scheme/	Programme:	MAINTENANCE	Se Mirda Lacka K Tak L Head 3054) (2016	Taih.
			Road Id No.:	5-17)
Status of the Project: Ongoing/Completed/Under Maintenance				
Work is	Work is a case of: New Connectivity/Up gradation/ Maintenance			
Sl. No.	的物质	Parameters to		Remarks
1	Pavement			
a)	Road Junction condition			√S/U
b)	Condition of Surfacing			v\$/U
c)	Riding Quality			√S/U
d)	Road Camber			√S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Wes/No
2	Cross Drainag	<b>C</b>		
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U			
b) 1	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			
3.	Road Furniture			S/SRI/U
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Gompliance History			The state of the s
a)	Status of ATR's & any others			Tours and the

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	951
Unsatisfactory (U)	DKI

NAME:

DESIGNATION:

(Signature)

Scanned with CamScanner