

FIELD INSPECTION REPORT

Date of Inspection :	02-12-2020	District:	GAYA
Division :	SHERGHATI	Length (km):	1.50 KM
Name of the Road:	BAR TO SALIYA		
Scheme/Programme:	MAINTENANCE	NEW MAINTENANCE POLICY 2018	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. <i>Not AV.</i>	Yes/No
f)	Contraction Joints provided or not (CC Pavement) <i>Not AV.</i>	Yes/No
g)	Compaction of flank/slope & raincuts if any <i>In progress</i>	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U <i>In progress</i>
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U <i>In progress</i>
c)	Condition of railings/slab/approach for Bridges	S/SRI/U <i>In progress</i>
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No <i>In progress</i>
4.	Compliance History	
a)	Status of ATR's & any others	<i>Not Any</i>

Overall Rating :

Satisfactory (S)	✓
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	—

Chud
02-12-2020
(Signature)

NAME:

MD. ASLAM

DESIGNATION:

J. E