

FIELD INSPECTION REPORT


Date of Inspection :	3.12.20	District :	Gurga
Division :	Shreeghahi	Length (km) :	4.70 km
Name of the Road :	E.T. Road to Pacharatan		
Scheme Programme :	MAINTENANCE		
Package No. :		Road Id No. :	
Status of the Project :	Ongoing / Completed / Under Maintenance		
Work is a case of :	New Connectivity / Up gradation / Maintenance		Remarks

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
	Work is not started.	S/U
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Work is not started.

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


3.12.20
(Signature)

NAME: chandra Lal Sumari
DESIGNATION: J.E.