

FIELD INSPECTION REPORT

Date of Inspection: 3-12-2020		District: GAYA	
Division: Neemchak Bathani		Length: Km: 1.5	
Scheme Programme:		MAINTENANCE	
Package No.: Construction for special Repair of Makhumpur more to Hathuvawan		Road Id No.:	
Status of the Project:		Ongoing Completed Under Maintenance	
Work is a case of:		New Connectivity Up gradation Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones Pavement road markings are provided and maintained	Yes/No	
4	Compliance History		
a)	Status of ATR's & any others.		

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

There is no provision of Routine maintenance in this Road

Chhetepal
3-12-2020
J.E