

# FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020		District : GAYA	
Location : Neemchak Bathani		Length (Km.) : 5.0 km	
Scheme/Programme:		MAINTENANCE Rd from Gaya-Khizersarai Rd to Baraki Bhediakala	
Project No. : MR-N/2019-20 Nimchak bathani/02		Road Id No. :	
Status of the Project :		Ongoing/Completed/Under Maintenance	
Work is a case of :		New Connectivity/Up gradation/Maintenance	
Parameters to be checked			Remarks
Pavement			S/U
Road Junction condition			S/U
Condition of Surfacing			S/U
Riding Quality			S/U
Road Camber			S/U
Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
Contraction Joints provided or not (CC Pavement)			Yes/No
Compaction of flank/slope & raincuts if any			Yes/No
Cross Drainage			S/SRI/U
Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
Condition of railings/slab/approach for Bridges			
Road Furniture			Yes/No
Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
Compliance History			
Status of ATR's & any others.			

Overall Rating :	
Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Note- Work has been not started.

Ram Basumatia

Am

3/12/2020