FIELD INSPECTION REPORT

Date of Inspection: 03.12.10			District: GVAM	
Division: RWD, Tekan Length (km): 3.500				
Name of the Road: KAR MAIN TO ANJTO.				
Scheme/Programme: MAINTENANCE - NMP -			NMP-2018	
Package No.:			Rond Id No.:	larde d
		Ongoing/Completed	/Under Maintenance = TUST &	towards
Work is a case of:			New Connectivity/Up gradation/ Maintenance	
Sl. Not Parameters to be elicefeed Remarks				
ī.	Payement			
a)	Road Junction condition			SVU
b)	Condition of Surfacing			SU
e)	Riding Quality			SU
d)	Road Camber			SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
0.	Contraction Joints provided or not (CC Pavement)			Yes No
g)	Compaction of flank/slope & raincuts if any			Yes No
2	Cross Drainage			
a)	Condition of head walls in Fulle pape curvers increased in			S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRLU
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			
a)	Status of ATR's & any others			
Overall Rating Sati		Satisfactory (S)		
Satisfactory bu			requires Improvement (\$RI)	N/A
Unsatisfactory (13/6

NAME: QUBHASH KUHAR-OR.