FIELD INSPECTION REPORT

D	Date of Inspection: 3. 12. 2020	District : GAYA	District : GAYA	
	ivison: Neemchak Bathani	Length (Km.: 4.0 km		
Scheme/Programme: MAINT		MAINTENANCE OLDER TO A COLOR	NANCE OLSE TOLL TOLL	
Pa	ckage No. : MR-N 2019-20 Ni	metak Bathani los	iwat	
Package No.: MR-N 2019-20 Nimetak Bathani 101 Road Id No.: Status of the Project:		Road Id No.:		
	ork is a case of:	Ongoing/Completed/Under Maintenance		
SI.		New Connectivity/Up gradation/Maintenance		
vo.		Parameters to be checked	Remarks	
1	Pavement		Kemarka	
3)	Road Junction condition			
)	Condition of Surfacing		S/U S/U	
=	Riding Quality Road Camber			
3				
1	Whether free from defects such as visible	cracks, exposed aggregates in case of CC Pavement.	S/U Yes/No	
	Contraction Joints provided or not (CC Pa	vement)	Yes/No	
1	Compaction of flank/slope & raincuts if ar	ny	Yes/No	
1	Cross Drainage	TO SEE STATE OF THE PARTY OF TH	1 65/140	
0	Condition of head walls in Hume pipe culv	verts including its painting	S/SRI/U	
	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U	
	Condition of railings/slab/approach for Bridges		S/SRI/U	
R	Road Furniture		3/3KI/U	
m	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
C	ompliance History			
St	atus of ATR's & any others.			

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

ND+e:- Easth work on progress

Ram babu manto J.E

Quy 3-12-2020 IE