

FIELD INSPECTION REPORT

Date of Inspection: 2-12-2020		District: GAYA
Division: Nirmal/Bathani		Length (Km.): 0.21
Scheme/Programme:		MAINTENANCE
Package No.:	Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance
Work is a case of:		New Connectivity/Up gradation/Maintenance
Sl. No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4	Compliance History	
a)	Status of ATR's & any others. ATR Not compliance	

Overall Rating :

Satisfactory (S)	SR1
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Chhatrapati
3-12-2020
T.G