FIELD INSPECTION REPORT

		THE THE	LITON REPORT		
Date of	Inspection:	02/12/2020	1	9.	
Division: Deachus			District: fatma. Length (km): 2.000 Km		
Name o	2.				
Name of the Road: Sakrai Cha Via Satachall to Kankatichak Scheme/Programme: MAINTENANCE					
Package No.: MB/N/20-21-Vansbur/ Package No.:					
Status of the Project: Ongoi			/Completed/Under Maintenance		
Work is a case of:		New Connectivity/Up gradation/ Maintenance			
SI; No.		Parameters to		Remarks	
1	Pavement				
a)	Road Junction	S/U			
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed yes/No				
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of	Yes/No			
22.11	Gross Dramage 17 17 17 17 17 17 17 17 17 17 17 17 17				
a)	Condition of he	S/SRI/U			
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3.	Road Furnitui	re i			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
4,	Complaince H	istory			
a)	Status of ATR's & any others				

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

World is not started.

Nigma
802/12/20

NAME: Nigmanand Mapto

(Signature)

DESIGNATION: