

FIELD INSPECTION REPORT

Date of Inspection : 03-12-2020	District: NAWADA
Division : RAJAWALI	Length (km): 3.90 KM
Name of the Road: Nawada Gaya Road (irrigation-office) to Talalpur-Sanokhara Road	
Scheme/Programme:	MAINTENANCE
Package No.: MR-N/19-20/Rajawali/04	Road Id No.: 10502601009
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No (To be done)
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	11/11
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature) *Binod*
03-12-2020

NAME: BINOD KUMAR

DESIGNATION: JUNIOR ENGINEER