

FIELD INSPECTION REPORT

Date of Inspection :	9.12.2020	District:	MAHARASHTRA
Division :	NAGAR	Length (km):	3.00 Km
Name of the Road:	DAGODAR ARIAR TO MOTI BIGHA KARAM CHAK		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	10502601015
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓/S
b)	Condition of Surfacing	✓/S
c)	Riding Quality	✓/S
d)	Road Camber	✓/S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓/S/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-


 (R.K. Sarvagat)
 J.R.
 NAME: RWD


 (Signature)
 3/12/20
 A.E.
 (ARUN SINGH)