## FIELD INSPECTION REPORT

Date of I	nspection: 3	12.2020	District: NAWADAY	
Division: MACOAM Length (km): 3-00/9				
Name of	the Road: "T	LAIYA BRITTEL		5146HD4
many or the same	Programme:	MAINTENANCI	And the control was a second of the control of the	in Control
ackage	makeness of the second state of the contract of the second state o		Road Id No.:	
and the same of th		Francisco (1) (1) (1)	Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance	
Mileton man our sign of	a case or		and the second s	Kemarks
Sl. No.	ak-toa konkonkon molda oldiko kurilarda oldiko koli (1945) e ak 1 syumba.	Parameters	to be checked	NUMAL NO
1.	Pavement			
a)	Road Junction condition			41
bi	Condition of Surfacing			
c)	Riding Quality			XI.
d)	Road Camber			1
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			YesNo
ľ)	Contraction Joints provided or not (CC Pavement)			Yes No
g)	Compaction of flank/slope & raincuts if any			165 %
2.	Cross Drainage			
a }	Condition of head walls in Hume pipe culverts including its painting			S SRIT
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			5 SR.
c)	Condition of railings/slab/approach for Bridges SSRU			SSRIT
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and mantaired			
4.	Compliance History			
a)	Status of ATR's & any others			
O	Daring		AND STATE OF THE S	_
Overall Rating :		Satisfactory (	The state of the s	5
		CONTRACTOR OF THE PROPERTY OF	out requires Improvement (SRI)	
		Unsatisfactor	) (U)	-

NAME: RUD

(Signature 12/12/20)
A-2
(ARUN SINGH)