FIELD INSPECTION REPORT

late of l	Inspection: 02-12-2020 District: NAWA	
livision	. Length (km): 1 · 3 ()	KM KM
iame of	THE ROAD FATEMPUR NARHAT ROAD to C	MANDEPUR
cheme/	Programme: MAINTENANCE	
ackage	No.: MIRN/2019-20 RATAULY Road Id No.: 1050261	02050
tatus o	f the Project: Ongoing/Completed/Under Maintenance	
Vork is	a case of: New Connectivity/Up gradation/ Maintenance	
SI. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	√S/U
b)	Condition of Surfacing	√\$/U
c)	Riding Quality	√SÂU
d)	Road Camber	√S/U
e)	Whether free from defects such as visible cracks, expose aggregates in case of CC Pavement.	d Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	g S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	s/sri/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	Road Furniture	1
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating

Satisfactory (S)	"S"	
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		

(Signature)

NAME: SINOD KLIMAR

DESIGNATION: JINIOR-ENGER