## FIELD INSPECTION REPORT

Date of 1	nspection: 02-12-2020 District: NAWADA		
-	1 48 (1). Da 410/	CM	
Name of	the Road: FATEHPUR NARHAT ROAD TO PAHA	RPHI	
Scheme	Programme:   MAINTENANCE		
Package	No.: MR N/2019-20 Rajan/or Road Id No.: 10 50 260	2051	
Status o	the Project: Ongoing/Completed/Under Maintenance		
Work is	a case of: New Connectivity/Up gradation/ Maintenance	Remarks	
Sl. No.	Parameters to be checked	Kemano	
1.	Payement		-
a)	Road Junction condition	√S/U	
b)	Condition of Surfacing	√\$/Ū	
c)	Riding Quality	√8fÚ	
d)	Road Camber	√s/u	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Ycs/No	NO C.C.
ſ)	Contraction Joints provided or not (CC Pavement)	Yes/No	MA
g)	Compaction of flank/slope & raincuts if any	\Yes/No	
2.	Gross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	√s/sri/u	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	s/sri/u	NIA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	] 174
3.	Road Furniture	1	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
<b>27.4.7</b>	Compliance History		
a)	Status of ATR's & any others	NA	
Overal	Rating : [aut aut aut aut aut aut aut aut aut aut	101	
- T - G   W	Satisfactory (S)	"5"	
	Satisfactory but requires Improvement (SRI)		

NAME: BINOD KLIMAR

DESIGNATION: JUNIOR ENVINEER

Unsatisfactory (U)

Scanned with CamScanner