


# FIELD INSPECTION REPORT

Date of Inspection :	3/12/2020	District:	Nawada
Division :	Nawada	Length (km):	2.400 KM
Name of the Road:	PWD Road to Arandpur		
Scheme/Programme:	MAINTENANCE		
Package No.:	MR-N/19-20/Nawada/13	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	<del>S/SRI</del>
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	<del>S/SRI</del>
c)	Condition of railings/slab/approach for Bridges	<del>S/SRI</del>
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

  
 3/12/2020  
 J. E. Nawada  
 (Signature)

NAME: