

FIELD INSPECTION REPORT

Date of Inspection :	03/12/2020	District:	Nagawadi
Division :	Nagawadi	Length (km):	1.40 km
Name of the Road:	Poh-Kawakol Road to Sighna		
Scheme/Programme:	MAINTENANCE		
Package No.:	MR-N/19-20/NW2/07	Road Id No.:	10502602138
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U N.A.
b)	Condition of Surfacing	S/U N.A.
c)	Riding Quality	S/U N.A.
d)	Road Camber	S/U N.A.
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N.A.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N.A.
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N.A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N.A.
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N.A.
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	X -
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

NAME:

[Signature]
03/12/2020
J.E. KAWAKOL
(SUTIT KUMAR)

[Signature]
03.12.2020

(Signature)

AE-KAWAKOL
(Raj Kishore Chauthay)