

FIELD INSPECTION REPORT

Date of Inspection :	02-12-2020	District:	NAWADA
Division :	RAJAWLI	Length (km):	
Name of the Road:	TELVADRO TO RAJAWLI		
Scheme/Programme:	MAINTENANCE		
Package No.:	MR-N/19-20/Rajawli/02	Road Id No.:	10502602159
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & mincuts if any	✓Yes/No
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

No C.C. paved
N/A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	5
Unsatisfactory (U)	

[Signature]
02/12/2020
(Signature)

NAME: SUMAN KUMAR
DESIGNATION: ASSISTANT ENGINEER