

# FIELD INSPECTION REPORT

Date of Inspection :	3.12.2020	District:	NAWADA
Division :	Nawada	Length (km):	1.6306
Name of the Road:	NH83 BAJRA		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	10502602150
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	✓
b)	Condition of Surfacing	✓
c)	Riding Quality	✓
d)	Road Camber	✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S SRI U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S SRI U
c)	Condition of railings/slab/approach for Bridges	S SRI U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

NAME: J.B. Ruid.  
3/12/20  
(R.K. Srivastava)

(Signature) 3/12/20  
A.B.  
(ARUN SINGH)