

FIELD INSPECTION REPORT

Date of Inspection :	3.12.2020	District:	NAUGADA
Division :	NAUGADA	Length (km):	2.50/4
Name of the Road:	NAUGADA-GAYA ROAD TO BHADISNI-BBLARU		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	10502602314
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/E ✓
b)	Condition of Surfacing	S/E ✓
c)	Riding Quality	S/E ✓
d)	Road Camber	S/E ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S SRI
c)	Condition of railings/slab/approach for Bridges	S SRI
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	-

Some pits develop on the road surface.

by
3/12/20
Chk. Srivastava
NAME: J.E. RAO

(Signature)
3/12/20
A.E.
(ARUN SINGH)