FIELD INSPECTION REPORT

ivision :	espection: 3.		Length (km): 1.1010		
Commission of the Commission o	The state of the s		11481714		
cheme/I	rogramme:	MAINTENANCE	White terms to a substitute of the substitute of		
ackage	No.:	Contraction and Contraction of the Contraction of t	Road Id No.: 10 5027 020	06	
	the Project:	Commission of the Commission o	d/Under Maintenance		
Vork is	a case of:	New Connectivity/	Up gradation/ Maintenance		
Sl. No.		Parameters to be checked		Remarks	
1.	Pavement				
n)	Road Junction condition			1	
bj	Condition of Surfacing			VI.	
c)	Riding Quality			181	
d)	Road Camber			1	
e)	Whether free from defects such as visible cracks, expused aggregates in case of CC Pavement.			Tex S	
1)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting S SRI			S SRI	
bi)	Condition of Abutment & Wing walls, Slab in RCC culverts			S SRITT	
e)	Condition of railings/slab/approach for Bridges SSR			SSRIV	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Meine	
4.	Compliance History				
a)	Status of ATR's & any others				
O	Il Patino				
Overall Rating :		Satisfactory (S)	>	
		Satisfactory by Unsatisfactory	at requires Improvement (SRI)	Manufacture at 11	

NAME: J'R RLOD.