

FIELD INSPECTION REPORT

Date of Inspection : 3/12/2020	District: Namadar
Division : Rajauli	Length (km): 6.3
Name of the Road: MACHUAPAHARI SAPHI - CHATKARI	
Scheme/Programme:	MAINTENANCE
Package No.: MR-N/19-20 Rajauli/12	Road Id No.: 10502702012
Status of the Project:	Ongoing/Completed/Under Maintenance <i>Ongoing</i>
Work is a case of:	New Connectivity/Up gradation/ Maintenance <i>Maintenance</i>

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & mincuts if any	Yes/No ✓
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	" S "
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

Amul
3/12/20
(Signature)

NAME: *Sunil Kumar*

DESIGNATION: *Assistant Engineer*