

FIELD INSPECTION REPORT

Date of Inspection : 2/12/2020		District: NAWADA	
Division : RAJAVLI		Length (km): 3.6	
Name of the Road: NH31 FARAKKA BUSJURG DHAMANI			
Scheme/Programme:		MAINTENANCE	
Package No.: MR-N/19-20 Rajavli/12		Road Id No.: 10502702018	
Status of the Project:		Ongoing/Completed/Under Maintenance <i>On going</i>	
Work is a case of:		New Connectivity/Up gradation/ Maintenance <i>Maintenance</i>	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		✓S/U
b)	Condition of Surfacing		✓S/U
c)	Riding Quality		✓S/U
d)	Road Camber		✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No <i>NA</i>
f)	Contraction Joints provided or not (CC Pavement)		Yes/No <i>NA</i>
g)	Compaction of flank/slope & rinecuts if any		Yes/No <i>NA</i>
2.	Gross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U <i>NA</i>
c)	Condition of railings/slab/approach for Bridges		S/SRI/U <i>NA</i>
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No <i>Work at to be Done</i>
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	(S)
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

Shubh
(Signature) 2/12/20

NAME: *Sumit Kumar*

DESIGNATION: *Assistant Engineer*