

# FIELD INSPECTION REPORT

Date of Inspection : 2/12/2020		District: Namada
Division : Rajauli		Length (km): 3.18
Name of the Road: NH31 SIMARKOL BANDHAN CHHAPRA		
Scheme/Programme: MAINTENANCE		
Package No.: MR-N/19-20 Rajauli/12		Road Id No.: 10502702019
Status of the Project: Ongoing/Completed/Under Maintenance		On going
Work is a case of: New Connectivity/Up gradation/ Maintenance		Maintenance
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & mincuts if any	Yes/No ✓
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No work at to be done
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	( " S " )
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

(Signature) Shruti  
2/12/20

NAME: Shruti Kumar

DESIGNATION: Assistant Engineer