

FIELD INSPECTION REPORT

Date of Inspection :	08/12/2020	District:	Nowadga
Division :	Raibaili	Length (km):	6.63 km
Name of the Road:	Saidpur Ghatag Bhikampur		
Scheme/Programme:	MAINTENANCE		
Package No.:	MRN/19-20/Raibaili/13	Road Id No.:	10502902024
Status of the Project:	Ongoing/Completed/Under Maintenance		Ongoing
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No } N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No }
g)	Compaction of flank/slope & raincuts if any	Yes/No } yet to be done
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U } yet to be done
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U }
c)	Condition of railings/slab/approach for Bridges	S/SRI/U }
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	S (S)
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

[Signature]
08/12/2020
(Signature)

NAME:

Ashok Kumar

DESIGNATION:

Asst. Engineer
Canningpur