## FIELD INSPECTION REPORT

	Inspection: () 2-12-2020 District: NAWAD	Δ
Date of I		
Division	: RATAULI Length (km): 2.256	BIGHA (
Name of		DIGHTICS
	Programme: MAINTENANCE	2027
	No.: mr-N/19-20/Rijadi/09   Road Id No.: 10 50260	2034
	the Project: Ongoing/Completed/Under Maintenance	
Work is	a case of: New Connectivity/Up gradation/ Maintenance	Remarks
Sl. No.	Parameters to be checked	Kemme
1.	Pavement	indian in the same
a)	Road Junction condition	√S/U
b)	Condition of Surfacing	√s/U
c)	Riding Quality	√5/U
d)	Road Camber	√s/u
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Ycs/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & mincuts if any	√Yes/No
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	√S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	XES/No
<b>20</b>	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	15"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	3.44

NAME: SLIMAN KLIMBR DESIGNATION: ASSISTANT- ENGINEER