## FIELD INSPECTION REPORT

	THE THE THE THE TAIL			
	Inspection: 03/12/2020 District: Nawada			
Division	: RATAULI Length (km): 1.172 K	1		
Name of	the Road: NH-31 to Barengark			
Scheme/	Programme: MAINTENANCE			
Package No.: mR-N/19-29 Rojcwil / 09 Road Id No.: 10502702044				
Status o	f the Project: Ongoing/Completed/Under Maintenance	. \		
Work is a case of: New Connectivity/Up gradation/ Maintenance				
Sl. No.	Parameters to be checked	Remarks		
1.	Pavement			
a)	Road Junction condition	√Ś/U		
b)	Condition of Surfacing	√S/U		
c)	Riding Quality	√S/U		
d)	Road Camber	√ <i>\$1</i> U	1000	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	NO C.C pavement	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	NA	
g)	Compaction of flank/slope & raincuts if any	√ es/No		
2.,	Gross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting	√S/SRI/U		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	s/srl/U	1/1/2	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U		
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	YES/No		
4.	Compliance History		E)	
8)	Status of ATR's & any others	N/A		
		- F1 - A //	7	

Overall Rating

	( C C !/
Satisfactory (S)	2.7
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: SUMAN-KUMAR
DESIGNATION: Assistant Engineer