

# FIELD INSPECTION REPORT

Date of Inspection : 03-12-2020	District: NAWADA
Division : RATAULT	Length (km): 7.930 km
Name of the Road: NH-30 PACHGAWAN MOR TO SARARPLHA	
Scheme/Programme: MAINTENANCE	
Package No.: MR-N/19-20/Pachgaw/06	Road Id No.: 10502702049
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & mincuts if any	✓Yes/No
2.	<b>Gross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	NA

No CC Pavement

NA

NA

Overall Rating :

Satisfactory (S)	"S"
Satisfactory but requires Improvement (SRI)	"
Unsatisfactory (U)	

(Signature) 03.12.2020

NAME:

BINOD KUMAR

DESIGNATION:

JUNIOR ENGINEER