

FIELD INSPECTION REPORT

Date of Inspection : 03-12-2021	District: Nawada
Division : Rajauli	Length (km): 1.460 KM
Name of the Road: Roh Seor to Mahraura	
Scheme/Programme:	MAINTENANCE
Package No.: MRN/1920 Rajauli-13	Road Id No.: 10502702055
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U -
b)	Condition of Surfacing	S/U NA
c)	Riding Quality	S/U - NA
d)	Road Camber	S/U - NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No - NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No - NA
g)	Compaction of flank/slope & raincuts if any	Yes/No - NA
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U - NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No - NA
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S X
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	X

NAME:

Arbind Kumar Sahu

DESIGNATION:

A.E. Roh

(Signature)
3/12/2021