

# FIELD INSPECTION REPORT

Date of Inspection : 2.12.2020	District: Aurangabad
Division : Daulnagar	Length (km): 1.400
Name of the Road: Haspura-Pisru road to Gahna.	
Scheme/Programme:	MAINTENANCE
Package No.:	Road Id No.:
Status of the Project:	<input checked="" type="checkbox"/> Ongoing/Completed/Under Maintenance
Work is a case of:	<input checked="" type="checkbox"/> New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	<b>Pavement</b>	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	<input checked="" type="checkbox"/> Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	N.A.

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Note - Work in Progress.

Sharma  
2.12.2020  
(Signature)

NAME: Nandan Sharma

DESIGNATION: J.E.