

FIELD INSPECTION REPORT

Date of Inspection :	03/12/2020	District:	Jahanabad
Division :	Jahanabad	Length (km):	2.60
Name of the Road:	Telhara road to Naina Pithamberpur		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U _m
b)	Condition of Surfacing	✓S/U _m
c)	Riding Quality	✓S/U _m
d)	Road Camber	✓S/U _m
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No NO
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U — N.A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U — N.A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

Arjun
03/12/20
(Signature)

NAME: ARJUN KUMAR

DESIGNATION: J.E