

FIELD INSPECTION REPORT

Date of Inspection : 02/12/2020		District: Jahanabad	
Division : Jahanabad		Length (km): 4.5 Km	
Name of the Road: OKSI to Paharpur			
Scheme/Programme: MAINTENANCE			
Package No.:		Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance			

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U ✓
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	S/U ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No — N.A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No — N.A
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U — N.A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U — N.A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	x
Satisfactory but requires Improvement (SRI)	x
Unsatisfactory (U)	'U'

Arjun
 02/12/2020
 (Signature)

NAME: ARJUN KUMAR

DESIGNATION: J.E