

FIELD INSPECTION REPORT

1 Block - Shahkum)
(Block - Shahkum)

Date of Inspection: 03/12/2020 | District: Bhagalpur

Division: Bhagalpur | Length (Km): 1.80KM

Name of the Road: Belthu to Manjho Road

Scheme/Programme: MAINTENANCE

Package No.: 07 | Road Id No.: 20703201006

Status of the Project: Ongoing / completed / Under Maintenance

Work is a case of : New Connectivity / Up gradation / Maintenance

SL. No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Cmpaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating : Work in Progress.

Satisfactory(S)	S
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory(U)	-

03/12/20
(Signature)

NAME: Neeraj Kumar

DESIGNATION: J.E