FIELD INSPECTION REPORT STOCK GOOD ATL

		
Date of I	nspection: 3.12.20 District: Byasalbur.	
Division:	(Goradily) Blogchbrol Length (Km): 1.400.	- Constitution of the Cons
Name of	the Road: PMGSy Road & Gestadih. to mulctabur	
Scheme,	/Programme: MAINTENANCE	
Package		
	f the Project: Ongoing /completed/Under Maintenance	
Work is	a case of : New Connectivity/Up gradation/ Maintenance	
SL. No.	Parameters to be checked	Remarks
1	Pavement	
a)	Road Junction condition	VS/U
b)	Condition of Surfacing	V5/U
c)	Riding Quality	V8/U
d)	Road Camber	s/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Cpmpaction of flank/slope & raincuts if any	A Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/I
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	No S/SRI/
c)		m S/SRI/
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 20 stones/Pavement road markings are provided and maintained	Om Yes/N
4	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating:

	6
Satisfactory(S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	

(Signature) 3/12/20

NAME: DIAL DEUSC.

DESIGNATION: -J. [