Date of Inspection: 3.12.20 District: Division: (Goradih) Bhyalbur | Length (Km): P.S. Kharama Satjori Sonudih main Roed Gorti. Name of the Road: Scheme/Programme: **MAINTENANCE** Road Id No .: 207 032 61022. Package No.: Ongoing /completed/Under Maintenance Status of the Project: New Connectivity/Up gradation/ Maintenance Work is a case of: Remarks Parameters to be checked SL. No. **Pavement** S/U Road Junction condition a) S/U Condition of Surfacing b) S/U **Riding Quality** c) S/U **Road Camber** d) NA. Whether free from defects such as visible cracks, exposed Yes/No e) aggregates in case of CC Pavement. Yes/No Contraction Joints provided or not (CC Pavement) f) Yes/No Cpmpaction of flank/slope & raincuts if any g) **Cross Drainage** 2 Condition of head walls in Hume pipe culverts including its painting S/SRI/U a) MA. Condition of Abutment & Wing Walls, Slab in RCC culverts S/SRI/U b) Condition of railings/slab/approach for Bridges S/SRI/U **Road Furniture** 3 Whether sign boards/informatory/cautionary Board/km & 200m Yes/No stones/Pavement road markings are provided and maintained a) 4 Compliance History MU. Status of ATR's & any others

Overall Rating:

Satisfactory(S)	
Satisfactory but requires Improvement (SRI)	" Lin
Unsatisfactory(U)	/

Note - wonce hers been sturted.

(Signature)

NAME: DINI- DUZL.

DESIGNATION: 7