FIELD INSPECTION REPORT

Block - Gwadih.

	alas acción
Date of Inspection: 3.12.20 District: - Blagal pur	
Division: (Gora dih) Bhagapun Length (Km): 3.700	
Name of the Road: PWD 12 red to Goody.	
Scheme/Programme: MAINTENANCE	
Package No.: Growl, - 01. Road Id No.: 20703201025.	
Status of the Project: Ongoing /completed/Under Maintenance	
Work is a case of : New Connectivity/Up gradation/ Maintenance	
SL. No. Parameters to be checked	Remarks
1 Pavement	
a) Road Junction condition	S/U
b) Condition of Surfacing	S/U
c) Riding Quality	s/U
d) Road Camber	s/U M
Whether free from defects such as visible cracks, exposed	Yes/No
aggregates in case of CC Pavement.	
f) Contraction Joints provided or not (CC Pavement)	Yes/No
g) Cpmpaction of flank/slope & raincuts if any	Yes/No
2 Cross Drainage	
a) Condition of head walls in Hume pipe culverts including its painting	s/sri/U [™]
b) Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U
serilings/slab/approach for Bridges	S/SRI/U
3 Road Furniture	00m
Whether sign boards/informatory/cautionary Board/km & 20 stones/Pavement road markings are provided and maintained	Yes/No
Compliance History	
a) Status of ATR's & any others	MA MO
Overall Rating:	
Satisfactory(S)	- IN
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	Y

lote. Work has been Started.

(Signature) 3.12.20

NAME: D.N. Devest.

DESIGNATION: - J.E.